

## MAHARASHTRA STATE ELECTRICITY TRANSMISSION COMPANY LTD.

## **Schedule of E-Tender Notice**

The tender document is available on the website https://srmetender.mahatransco.in which can be downloaded by the bidder. Summary of the e-tender notice is as follows:

Sr. No.	E-Tender Reference	Particulars
1	E-Tender No.	SP/T-0802/0225 [1 <sup>st</sup> Call]
2	RFX No	5000001374
3	Subject of E-Tender	Procurement of SF6 Gas Handling Unit, SF6 Gas Analyzer & SF6 Gas Leak Detector. [1 <sup>st</sup> Call]
4	Estimated Cost of Tender	<b>Rs. 803.08 Lakhs</b> (Eight Hundred Three Lakhs And Eight Thousand Only) (Inclusive of all Taxes)
5	E-Tender Fees	Rs. 5000 + GST non-refundable (to be paid online)
6	EMD	@1% of estimated value of the tender (Inclusive of all Taxes)
7	Date and time for sale of bid documents	From 12.02.2025, 19:00 Hrs.
8	Pre-bid meeting Date, Time & Venue	Date: 17.02.2025 Time: 15:00:00 Hrs. Venue: 4 <sup>th</sup> Floor, MSETCL C.O. 'Prakashganga' Plot No. C-19, E-Block, Bandra Kurla Complex, Bandra East, Mumbai, Maharashtra 400051
10	Last date and time for submission of request for amendment/ clarification in the tender	On or before 19.02.2025
11	Due Date & Time of Submission of Bid	05.03.2025, 17:00 Hrs.
12	Due Date & Time of Opening of Bid	05.03.2025, 17:30 Hrs.
13	Contact Person	<ol> <li>C.E. (CPA) (I/C)</li> <li>E.E. (Group-VIII),</li> <li>CPA, C.O. MSETCL, 1<sup>st</sup> Floor, Prakashgad Building, Bandra (E), Mumbai</li> <li>Email id: <u>cecpa@mahatransco.in</u> <u>eegrp8@mahatransco.in</u></li> </ol>

Note:

- a. The tender documents can be downloaded only online from aforesaid website, within period of advertisement of tender.
- b. The bidder shall submit their appropriate bids (Technical & Commercial) online, well in advance within due date & time indicated in the RFx. No extension to bid submission date & time will be given.
- c. The Techno-Commercial Bid and Price Bid will be opened on SRM e-Tendering portal.
- d. MSETCL will not be responsible for non-submission of bid due to any website related issues.